

<p>ESCORT/VERONA</p>  <p>02684 30.420 LD 02683 30.419 LE</p>	<p>FUSCA/VARIANT</p>  <p>07998 CR-10120 01806 20.420</p>	<p>GOL 95/ GII GRANDE</p>  <p>02666 21.222 LD 02665 21.221 LE</p>	<p>GOL 95/ GII PEQUENO</p>  <p>02668 21.224 LD 02667 21.223 LE</p>	<p>OPALA 2 PORTAS CARRINHO</p>  <p>01738 40.166</p>
---	---	--	--	---

<p>BRASILIA</p>  <p>02678 20.424 LD 05536 W-126 LD 02679 20.425 LE 05535 W-125 LE</p>	<p>CAMINHÕES VW TODOS</p>  <p>03481 20.635 LD/LE</p>	<p>CHEVETTE /82</p>  <p>02137 40.151 LD/LE</p>	<p>CHEVETTE 83/</p>  <p>02138 40.112 LD/LE</p>	
<p>CORCEL II/DEL REY</p>  <p>02681 30.256 LD 02682 30.257 LE</p>	<p>CORSA 2 PORTAS</p>  <p>05531 M-107 LD/LE</p>	<p>CORSA 4 PORTAS</p>  <p>05532 M-108 LD 17722 M-109 LE</p>	<p>D10/D60 64/84</p>  <p>02660 40.195 LD/LE</p>	<p>D20 D40 /88</p>  <p>02662 40.368 LD/LE</p>
<p>D20 D40 89/</p>  <p>05513 D-020 LD/LE</p>	<p>ESCORT/VERONA</p>  <p>02680 30.221 LD/LE</p>	<p>F1000 /92</p>  <p>01983 30.258 LD/LE 08418 CR-10171 LD/LE 05516 F-102 LD/LE</p>	<p>F1000 93/</p>  <p>03332 30.822 LD/LE 08417 CR-10145 LD/LE</p>	
<p>FIESTA</p>  <p>05517 F-103 LD/LE</p>	<p>FUSCA 1300/1500/1600</p>  <p>01130 20.421 LD/LE 08010 CR-10195 LD/LE 05534 W-035 LD/LE</p>	<p>GOL /94</p>  <p>01160 20.460 LD/LE 05539 CR-10196 LD/LE</p>	<p>GOL 95/ 2/4PTS GII/GIII</p>  <p>02669 20.806 LD/LE 05538 W-404 LD/LE</p>	
<p>KADETT</p>  <p>05514 D-100 LD/LE</p>	<p>KOMBI CLIPPER</p>  <p>02677 20.423 LD/LE 05540 W-562 LD/LE</p>	<p>LOGUS</p>  <p>05528 L-101 LD/LE</p>	<p>MBB 85/89</p>  <p>03387 50.206 LD/LE</p>	<p>MBB 1113/1313/1513/1929</p>  <p>01735 50.160 LD/LE</p>
<p>MONZA</p>  <p>02071 40.367 LD/LE 05530 M-106 LD/LE</p>	<p>OPALA 2PTS</p>  <p>01123 40.232 LD 01124 40.233 LE</p>	<p>OPALA 4PTS CARAVAN</p>  <p>02661 40.234 LD/LE</p>	<p>PASSAT</p>  <p>02676 20.422 LD/LE 05537 W-210 LD/LE</p>	<p>S10/BLAZER 95/</p>  <p>05529 M-105 LD/LE</p>
<p>SANTANA/QUANTUM</p>  <p>02074 20.653 LD/LE 05533 S-007 LD/LE</p>	<p>SCANIA</p>  <p>01589 60.145 LD/LE</p>	<p>TOYOTA</p>  <p>03586 60.326 LD/LE</p>	<p>UNO/PREMIO/ELBA</p>  <p>02825 60.796 LD/LE 05527 I-018 LD/LE</p>	<p>PALIO/TEMPRA/DUCATO GUIA LATERAL (DESLIZE DO VIDRO)</p>  <p>09125 P-23</p>